

Daftar Lelang Floor Mobil - LELANG ONLINE VAGANZA TIMUR | 20/07/2026 (84)

KOTA LELANG ONLINE VAGANZA TIMUR (LOV) / -

KATALOG INI HANYA SEBAGAI PANDUAN SAJA. BUKAN SEBAGAI PEDOMAN ATAU SEBAGAI BAHAN ACUAN COMPLAIN

SmartBID melelang unit apa adanya, peserta lelang wajib melakukan cek fisik kendaraan dan dokumen dengan sebaik-baiknya. Pemenang lelang telah dianggap sudah memahami kondisi dan dokumen kendaraan yang telah dimenangkan. Deposit dan pelunasan unit Lelang SmartBID hanya melalui transfer Bank Central Asia, Tbk (BCA) a/n PT. Anugerah Lelang Indonesia, nomor rekening : 4688897988 (Sidoarjo), 4686088588 (Semarang), 4687088688 (Tangerang), 4688670088 (Makassar) .

Note:
Setiap unit dikenakan biaya administrasi sebesar: **Rp. 3.500.000,-**
Khusus untuk unit dengan harga terbentuk di atas **Rp. 350.000.000,-** dikenakan admin fee 1% dari harga terbentuk.

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
1	DT 8634 DH	MITSUBISHI FE 75	2023	MT	3907	KUNING	RP147.000.000	SOLAR	0	E	E	F	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC ARDIAZ 082142028080 // //CASHBACK SEBESAR:RP3,500,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
2	B 9097 FAW	SUZUKI CARRY PU	2020	MT	1462	HITAM	RP62.000.000	BENSIN	188492	E	C	D	14 HARI KERJA	ADA 2025-10-08	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //SAPUTRA 089614641697// KEUR HANYA ADA MASA BERLAKU // KARTU KEUR TA // //CASHBACK SEBESAR:RP3,500,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
3	PA 8739 GZ	TOYOTA HILUX 2.5 E 4X4 DC	2014	MT	2494	PUTIH	RP45.000.000	SOLAR	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
NOPOL FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. RISON 0812-4751-9346 / CS PUSAT 081188089292// BODY BARET, BUMPER BARET, CAT KUSAM, MESIN MATI TERBURAI TIDAK LENGKAP, LAMPU KUSAM PECAH DAN TIDAK LENGKAP, FOOGLAMP T/A, PENNUTUP BAK IMITASI, VELG PENYOK DAN IMITASI, STIR RUSAK, HEAD UNIT T/A, INTERIOR KOTOR, AIRBAG T/A, BAN GUNDUL, TRANSMISI INDIKASI BONGKARAN, POWER WINDOW T/A.//SHOCBREAKERS (FR) ECU TIRE (RR-L) TIRE (SPARE) BRAKE PAD (FR) DYNAMO STARTER GASKET CYLINDER HEAD RADIATOR FAN TIRE (RR-R) GASKET COVER HEAD RIM (SPARE) POWER STEERING TIRE (FR-R) HEADER FUEL PUMP COIL IGNITION DINAMO STARTER SPRING (FR) ENGINE MOUNTING DISC PAD AIRCON EVAPORATOR RIM (RR-R) SHOCBREAKERS (RR) FAN BELT AIRBAG WHEEL BEARING (FR) INJECTOR SPARK PLUG(S) TIRE (FR-L) BRAKE PAD (RR) SPRING (RR) BRAKE MASTER AIR FILTER ENGINE BLOCK RACK STEER RIM (FR-L) CLUTCH PLATE WHEEL BEARING (RR) RIM (FR-R) RIM (RR-L) RADIATOR BATTERY/BOLT CRANE AND JACK STEERING-WHEEL HEAD UNIT CARSEAT (FR-R) POWER-WINDOW PANEL (FR-R) CEILING TRIM CARPET INTERIOR SALOON CARSEAT (FR-L) TOOL KIT/RR-DOOR GLASS (R) DOOR REPAIR (FR-R) FOG LAMP (L) TAILLIGHT (RR-L) TURN LAMP (RR-L) TAILLIGHT (RR-R) FR-DOOR GLASS (L) FR-DOOR GLASS (R) ELECTRIC MIRROR (L) TURN LAMP (RR-R) CARGO PANEL REPAIR (RR) FOG LAMP (R) RR-DOOR GLASS (L) ELECTRIC MIRROR (R) ENGINE HOOD REPAIR BUMPER REPAIR (FR) TURN LAMP (FR-R) HEADLIGHT (FR-R) TURN LAMP (FR-L) DOOR REPAIR (RR-R) BUMPER REPAIR (RR) DOOR REPAIR (RR-L) HEADLIGHT (FR-L) ROOF REPAIR DOOR REPAIR (FR-L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
4	F 8197 HR	SUZUKI CARRY PU	2022	MT	1462	HITAM	RP62.000.000	BENSIN	0	E	E	F	14 HARI KERJA	ADA 2026-04-08	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //SAPUTRA 089614641697// //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
5	DC 1181 AU	TOYOTA AVANZA 1.3 E	2016	MT	1329	SILVER METALIK	RP65.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. PAUL 0823-1581-4593 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES & PENYOK, ACCU SUAK, ALARM T/A, KLAKSON TIDAK BERFUNGSI, ALAT MOBIL T/A, HEADREST TIDAK LENGKAP, KACA DEPAN RETAK, COVER JOK IMITASI, MESIN REMBES OLI, BULLHEAD BERKARAT (REKONDISI), VELG IMITASI, KONDISI BAN GUNDUL, INDIKASI UNIT EX-LAKA DEPAN KANAN/SPARE KEY (IMMOBILIZER) REMOTE RADIATOR TIRE (RR-L) TIRE (FR-L) TIRE (SPARE) RIM (FR-L) RIM (FR-R) RIM (RR-R) ENGINE SERVICES (LIGHT) AIRCON EVAPORATOR RADIATOR FAN RIM (SPARE) RIM (RR-L) BRAKE PAD (FR) BRAKE PAD (RR) FR-APRON SPARK PLUG(S) BRAKE MASTER TIRE (RR-R) GASKET COVER HEAD R-APRON SPRING (RR) CLUTCH BEARING RACK STEER FAN BELT SPRING (FR) GASKET CYLINDER HEAD BATTERY INJECTOR CLUTCH PLATE TIRE (FR-R)/CEILING LAMP (FR) INTERIOR MIRROR HEADREST (FR-R) HEADREST (RR-L) CEILING LAMP (RR) CARPET FLOOR (RR) CONSOLE BOX CEILING TRIM INTERIOR SALOON CARPET FLOOR (FR-R) TOOL KIT HORN CARPET FLOOR (MID) HEADREST (RR-R) CARPET BOLT CRANE AND JACK AIRCON PANEL HEADREST (FR-L) CARPET FLOOR (FR-L)/RIM COVER (FR-L) TURN LAMP (RR-L) WINDSHIELD GLASS SIDE SKIRT REPAIR (L) TURN LAMP (FR-L) TAILLIGHT (RR-R) HEADLIGHT (FR-R) TURN LAMP (RR-R) TAILLIGHT (RR-L) RIM COVER (RR-L) GRILLES TURN LAMP (FR-R) RIM COVER (FR-R) HEADLIGHT (FR-L) SIDE SKIRT REPAIR (R) RIM COVER (RR-R) ANTENNA MIRROR (R) DOOR REPAIR (FR-R) MIRROR (L) ENGINE HOOD REPAIR WINDSHIELD WIPER ROOF REPAIR FENDER REPAIR (RR-R) FENDER REPAIR (FR-R) DOOR REPAIR (RR-R) FENDER REPAIR (RR-L) DOOR REPAIR (TRUNK) DOOR REPAIR (FR-L) FENDER REPAIR (FR-L) EMBLEM BUMPER REPAIR (RR) DOOR REPAIR (RR-L) BUMPER REPAIR (FR)) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
6	DD 1529 UE	TOYOTA INNOVA	2008	MT	1998	HITAM METALIK	RP32.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-01-06	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
FOTO NOKA & NOSIN BERKARAT // PEMENANG LELANG WAJIB TTD SURAT PERNYATAAN DIATAS MATERAI // STNK HANYA FOTO SCAN // NOPOL FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // LOKASI UNIT HUBUNGI PIC BPK. PAUL 0823-1581-4593 / CS PUSAT 081188089292//UNIT LAKA LANTAS, BULLHEAD PENYOK, NOMOR RANGKA BERKARAT, CHASIS PENYOK, MESIN TIDAK BERFUNGSI, BAN CADANGAN T/A, HEAD UNIT T/A, ALAT MOBIL T/A, SPOILER T/A, KACA SPION T/A, BUMPER DEPAN T/A & BUMPER BELAKANG RUSAK (TERLEPAS), HEADREST T/A, SEATBELT TIDAK LENGKAP//RADIATOR FAN CLUTCH PLATE FR-APRON RIM (RR-R) CHASSIS RADIATOR BRAKE PAD (FR) CLUTCH BEARING BRAKE PAD (RR) TIRE (FR-R) SPRING (RR) BATTERY GASKET COVER HEAD SPRING (FR) ENGINE SERVICES (LIGHT) TIRE (SPARE) BRAKE MASTER RIM (SPARE) FAN BELT TIRE (FR-L) TIRE (RR-L) RACK STEER SPARK PLUG(S) GASKET CYLINDER HEAD TIRE (RR-R) AIRCON EVAPORATOR INJECTOR RIM (RR-L)/HEADREST (RR-R) HEADREST (M-L) HEADREST (FR-R) SUNVISOR L CARPET FLOOR (MID) HEAD UNIT AIRCON PANEL HEADREST (M-R) BOLT CRANE AND JACK SUNVISOR R INTERIOR MIRROR SEATBELT (RR-L) CEILING LAMP (RR) HEADREST (RR-L) HEADREST (FR-L) DASHBOARD INTERIOR SALOON TOOL KIT CEILING LAMP (FR) CARPET FLOOR (FR-R) CARPET FLOOR (FR-L) CARPET CARPET FLOOR (RR) CEILING TRIM SEATBELT (RR-R)/FENDER REPAIR (RR-L) RIM COVER (RR-R) DOOR REPAIR (RR-R) ANTENNA WINDSHIELD WIPER HEADLIGHT (FR-R) LICENSE PLATE FOG LAMP (L) TAILLIGHT (RR-R) TURN LAMP (FR-R) SIDE SKIRT REPAIR (L) ENGINE HOOD REPLACE ELECTRIC MIRROR (R) BUMPER REPLACE (RR) MIRROR (R) DOOR REPAIR (FR-L) FENDER REPLACE (FR-R) RIM COVER (FR-R) DOOR REPAIR (RR-L) HEADLIGHT (FR-L) RIM COVER (RR-L) SPOILER (RR) RIM COVER (FR-L) DOOR REPAIR (FR-R) ROOF REPAIR EMBLEM TURN LAMP (RR-L) BUMPER REPLACE (FR) ELECTRIC MIRROR (L) SIDE SKIRT REPAIR (R) FENDER REPLACE (FR-L) TURN LAMP (RR-R) FOG LAMP (R) MIRROR (L) TURN LAMP (FR-L) DOOR REPAIR (TRUNK) GRILLES TAILLIGHT (RR-L) FENDER REPAIR (RR-R) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
7	PA 1784 GW	DAIHATSU TERIOS X	2022	MT	1496	SILVER METALIK	RP75.500.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
NOPOL PADA FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. RISON 0812-4751-9346 / CS PUSAT 081188089292// KONDISI UNIT LAKA LANTAS, RUSAK BAGIAN DEPAN, CHASIS BULLHEAD KAPMESIN BENGKOK PENYOK, LAMPU RUSAK KUSAM PECAH, BUMPER RUSAK, KACA PECAH, BUMPER BLAKANG T/A, KACA PECAH, MESIN MUNDUR, INTERIOR KUSAM, CHASIS PENYOK DEPAN.//CHASSIS WHEEL AXELS (FR) ABS INDIKATOR ABS INDIKATOR DYNAMO STARTER FUEL PUMP SPRING (FR) RIM (FR-R) FR-APRON GASKET CYLINDER HEAD TIRE (RR-L) WHEEL BEARING (RR) FAN BELT TIRE (RR-R) INJECTOR SPARK PLUG(S) TIRE (SPARE) R-APRON BRAKE PAD (RR) RIM (RR-L) SHOCBREAKERS (RR) RIM (FR-L) TIRE (FR-L) CLUTCH BEARING GEAR BOX OVERHAUL SHOCBREAKERS (FR) POWER STEERING WHEEL AXELS (RR) RADIATOR FAN BRAKE MASTER GASKET COVER HEAD ENGINE MOUNTING ENGINE SERVICES (HEAVY) MUFFLER AIRCON EVAPORATOR HEADER TIRE (FR-R) COIL IGNITION SPRING (RR) RIM (SPARE) RIM (RR-R) BATTERY L-APRON WHEEL BEARING (FR) RACK STEER CLUTCH PLATE DISC PAD RADIATOR BRAKE PAD (FR)/CARPET FLOOR (RR) HEAD UNIT CARPET CARPET FLOOR (FR-R) CARPET FLOOR (FR-L) INTERIOR SALOON CARPET FLOOR (MID) TOOL KIT BOLT CRANE AND JACK/FENDER REPLACE (FR-R) FENDER REPLACE (RR-L) ENGINE HOOD REPLACE TURN LAMP (FR-L) TURN LAMP (RR-R) ROOF REPAIR ELECTRIC MIRROR (R) DOOR REPAIR (FR-R) TURN LAMP (FR-R) FR-DOOR GLASS (L) HEADLIGHT (FR-R) HEADLIGHT (FR-L) FR-DOOR GLASS (R) FOG LAMP (R) TAILLIGHT (RR-L) DOOR REPAIR (FR-L) WINDSHIELD GLASS TAILLIGHT (RR-R) DOOR REPAIR (TRUNK) ELECTRIC MIRROR (L) FOG LAMP (L) DOOR REPAIR (RR-L) TURN LAMP (RR-L) BUMPER REPLACE (FR) DOOR REPAIR (RR-R) BUMPER REPLACE (RR) RR-VENT GLASS (L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
8	B 1937 TFR	DAIHATSU XENIA	2009	MT	1298	HITAM METALIK	RP47.000.000	BENSIN	307649	D	C	D	14 HARI KERJA	ADA 2024-10-05	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //SAPUTRA 089614641697 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
9	T 1576 HR	TOYOTA AGYA 1.2 G	2022	MT	1197	KUNING	RP106.000.000	BENSIN	21052	C	C	C	14 HARI KERJA	ADA 2025-08-29	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU //SAPUTRA 089614641697// //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
10	KT 1219 YD	HONDA BRIO SATYA DD1 1.2 E	2015	MT	1198	MERAH	RP71.000.000	BENSIN	255588	D	C	D	14 HARI KERJA	ADA 2026-08-20	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC HAKIM +62 852-4141-5636 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
11	PT 8723 AA	TOYOTA HILUX 4X2 2.0 PU	2019	MT	1998	HITAM METALIK	RP49.500.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. DEDY 0812-7358-6232 / CS PUSAT 081188089292// UNIT RUSAK, NOKA TIPIS, BODY PENYOK BARET KEROPOS, BAK PENYOK KEROPOS KARAT, KACA PECAH, PLAFON T/A, INTERIOR KOTOR, LAMPU KUSAM DAN PECAH, KACA BELAKANG T/A, BUMPER T/A, BULLHEAD BENGKOK, BAN GUNDUL, MESIN RUSAK (TURUN MESIN), MESIN REMBES OLI.//SPRING (FR) COIL IGNITION HEADER SPRING (RR) AIR FILTER GASKET COVER HEAD RIM (FR-R) CEK ENGINE LIGHT GEAR BOX OVERHAUL TIRE (SPARE) GASKET CYLINDER HEAD FAN BELT TIRE (RR-R) RIM (FR-L) L-APRON DINAMO STARTER RIM (RR-R) RIM (RR-L) ENGINE MOUNTING FR-APRON RIM (SPARE) FUEL PUMP WHEEL BEARING (RR) BRAKE PAD (FR) RACK STEER CLUTCH PLATE MUFFLER SHOCBREAKERS (RR) TIRE (FR-L) BRAKE MASTER TIRE (RR-L) R-APRON BRAKE PAD (RR) DISC PAD ENGINE SERVICES (HEAVY) RADIATOR SHOCBREAKERS (FR) TIRE (FR-R) WHEEL BEARING (FR) BATTERY SPARK PLUG(S) AIRCON EVAPORATOR RADIATOR FAN DYNAMO STARTER/HEAD UNIT STEERING-WHEEL INTERIOR SALOON TOOL KIT CARSEAT (FR-L) CEILING TRIM CARSEAT (FR-R) BOLT CRANE AND JACK CARPET/FOG LAMP (L) DOOR REPAIR (RR-R) DOOR REPAIR (FR-L) DOOR REPAIR (RR-L) ROOF REPAIR BACK GLASS CARGO PANEL REPLACE WINDSHIELD GLASS TURN LAMP (RR-R) TAILLIGHT (RR-L) TURN LAMP (FR-L) TURN LAMP (FR-R) FOG LAMP (R) HEADLIGHT (FR-L) HEADLIGHT (FR-R) FENDER REPAIR (FR-L) DOOR REPAIR (FR-R) ENGINE HOOD REPAIR BUMPER REPLACE (FR) FENDER REPAIR (FR-R) TURN LAMP (RR-L) TAILLIGHT (RR-R) LICENSE PLAT //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
12	DB 1394 LE	TOYOTA AVANZA VELOZ	2016	MT	1496	HITAM METALIK	RP101.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

[DICETAK TGL. 18-07-2026]

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
NOPOL PADA FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK FAHMI/BPK. USMAN 0821-8761-0965 / 0823-9133-7272 // CS PUSAT 081188089292// BODY BARET, BUMPER BARET, INTERIOR KUSAM, LAMPU KUSAM, MESIN REMBES OLI, BAN DAN VELG IMITASI, INDIKASI UNIT LINTAS ANTAR KABUPATEN.//RIM (FR-L) SPRING (FR) ENGINE SERVICES (HEAVY) TIRE (FR-L) FUEL PUMP TIRE (FR-R) COIL IGNITION GASKET COVER HEAD RIM (SPARE) GASKET CYLINDER HEAD RIM (FR-R) RIM (RR-R) RIM (RR-L) SPRING (RR) WHEEL BEARING (FR) HEADER TIRE (SPARE) TIRE (RR-R) TIRE (RR-L) SHOCBREAKERS (RR) CLUTCH PLATE WHEEL BEARING (RR) BRAKE PAD (RR) RACK STEER CLUTCH BEARING FAN BELT RADIATOR RADIATOR FAN AIRCON EVAPORATOR DISC PAD BRAKE PAD (FR) SHOCBREAKERS (FR) INJECTOR SPARK PLUG(S) BATTERY BRAKE MASTER/CARSEAT (FR-L) CARSEAT (FR-R) CARPET FLOOR (RR) CARPET CARPET FLOOR (FR-R) TOOL KIT BOLT CRANE AND JACK CARPET FLOOR (MID) CARPET FLOOR (FR-L) INTERIOR SALOON/HEADLIGHT (FR-R) HEADLIGHT (FR-L) DOOR REPAIR (RR-R) TURN LAMP (FR-R) TURN LAMP (RR-L) TAILLIGHT (RR-R) FOG LAMP (R) FOG LAMP (L) BUMPER REPAIR (FR) TAILLIGHT (RR-L) TURN LAMP (RR-R) DOOR REPAIR (FR-R) TURN LAMP (FR-L) DOOR REPAIR (FR-L) DOOR REPAIR (TRUNK) DOOR REPAIR (RR-L) ROOF REPAIR BUMPER REPAIR (RR) ENGINE HOOD REPAIR //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
21	DD 1620 XES	TOYOTA INNOVA G	2008	MT	1998	HITAM METALIK	RP78.500.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. MASSUARAH 0813-5561-8851 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES (CAT ULANG), ALAT MOBIL T/A, HEAD UNIT IMITASI, PENUTUP LACI DASHBOARD T/A, MESIN REMBES OLI, SEATBELT TIDAK LENGKAP, DOORTRIM BAGASI T/A, SPARKBOARD T/A//SHOCBREAKERS (RR) SHOCBREAKERS (FR) TIRE (RR-L) TIRE (SPARE) MUFFLER ENGINE SERVICES (LIGHT) TIRE (FR-R) GASKET COVER HEAD SPRING (RR) SPRING (FR) FAN BELT TIRE (RR-R) RADIATOR GASKET CYLINDER HEAD CLUTCH PLATE RACK STEER RADIATOR FAN TIRE (FR-L) SPARK PLUG(S) AIRCON EVAPORATOR BRAKE PAD (FR) CLUTCH BEARING BRAKE MASTER INJECTOR BRAKE PAD (RR) BATTERY/CEILING TRIM TOOL KIT CARPET FLOOR (MID) DOOR TRIM (TRUNK) INTERIOR SALOON SEATBELT (RR-L) SEATBELT (RR-R) CARPET FLOOR (FR-R) CARPET FLOOR (RR) CARPET FLOOR (FR-L) BOLT CRANE AND JACK DASHBOARD CARPET HEAD UNIT/RIM COVER (FR-L) FOG LAMP (R) TURN LAMP (RR-L) EMBLEM ROOF REPAIR WINDSHIELD WIPER RIM COVER (RR-R) TAILLIGHT (RR-L) DOOR REPAIR (TRUNK) RIM COVER (FR-R) FOG LAMP (L) RIM COVER (RR-L) TAILLIGHT (RR-R) HEADLIGHT (FR-R) MIRROR (R) SIDE SKIRT REPAIR (L) ENGINE HOOD REPAIR TURN LAMP (FR-R) BUMPER REPAIR (FR) TURN LAMP (FR-L) MIRROR (L) TURN LAMP (RR-R) HEADLIGHT (FR-L) FENDER REPAIR (RR-L) BUMPER REPAIR (RR) FENDER REPAIR (RR-R) SIDE SKIRT REPAIR (R) FENDER REPAIR (FR-R) FENDER REPAIR (FR-L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
22	DT 1971 AM	TOYOTA AVANZA G	2012	MT	1298	PUTIH	RP68.500.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-03-30	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. FERDY 0822-4916-6365 / CS PUSAT 081188089292//MESIN BERFUNGSI (KASAR), BODY TERGORES, AC TIDAK DINGIN, BAN CADANGAN T/A, ALAT MOBIL T/A, KACA SPION T/A, SETIR IMITASI, HEAD UNIT IMITASI, COVER PLAFON IMITASI, HEADREST TIDAK LENGKAP, MESIN REMBES OLI, JOK BARIS KETIGA T/A, CONSOLE BOX T/A//RIM (SPARE) GASKET COVER HEAD SPRING (FR) RIM (RR-R) GASKET CYLINDER HEAD MUFFLER RADIATOR TIRE (SPARE) TIRE (RR-L) TIRE (FR-R) BATTERY SPRING (RR) BRAKE PAD (RR) BRAKE MASTER TIRE (FR-L) RACK STEER INJECTOR SPARK PLUG(S) RADIATOR FAN CLUTCH BEARING TIRE (RR-R) CLUTCH PLATE AIRCON EVAPORATOR FAN BELT ENGINE SERVICES (LIGHT) BRAKE PAD (FR)/CEILING LAMP (FR) HEADREST (RR-L) CEILING LAMP (RR) CARPET HEADREST (RR-R) HEADREST (FR-L) CARSEAT (RR-L) CEILING TRIM CARSEAT (RR-R) CARPET FLOOR (FR-R) CARPET FLOOR (MID) CARPET FLOOR (RR) HEADREST (FR-R) BOLT CRANE AND JACK TOOL KIT CARPET FLOOR (FR-L) STEERING-WHEEL CONSOLE BOX INTERIOR SALOON HEAD UNIT/HEADLIGHT (FR-L) EMBLEM TAILLIGHT (RR-L) TURN LAMP (FR-L) RIM COVER (RR-L) HEADLIGHT (FR-R) TURN LAMP (RR-L) LICENSE PLATE TURN LAMP (RR-R) TURN LAMP (FR-R) ELECTRIC MIRROR (R) RIM COVER (RR-R) FOG LAMP (L) RIM COVER (FR-R) ANTENNA SIDE SKIRT REPAIR (L) RIM COVER (FR-L) ENGINE HOOD REPAIR FENDER REPAIR (FR-R) FOG LAMP (R) WINDSHIELD WIPER DOOR REPAIR (TRUNK) ELECTRIC MIRROR (L) SIDE SKIRT REPAIR (R) MIRROR (R) TAILLIGHT (RR-R) BUMPER REPAIR (RR) FENDER REPAIR (RR-L) BUMPER REPAIR (FR) MIRROR (L) FENDER REPAIR (RR-R) FENDER REPAIR (FR-L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
23	DN 1765 CY	TOYOTA YARIS G	2017	MT	1497	HITAM METALIK	RP139.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2025-10-14	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. RUDOLF 0812-4270-3822 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES (GANTI WARNA), KNALPOT IMITASI, HEAD UNIT IMITASI//RIM (SPARE) RADIATOR SPRING (RR) GASKET CYLINDER HEAD ENGINE SERVICES (LIGHT) SPRING (FR) TIRE (RR-L) GASKET COVER HEAD TIRE (RR-R) RADIATOR FAN TIRE (FR-L) CLUTCH PLATE WHEEL BEARING (RR) TIRE (SPARE) SPARE KEY (IMMOBILIZER) MUFFLER TIRE (FR-R) SPARK PLUG(S) BATTERY INJECTOR BRAKE PAD (FR) BRAKE MASTER CLUTCH BEARING WHEEL BEARING (FR) FAN BELT BRAKE PAD (RR) AIRCON EVAPORATOR/CEILING TRIM CEILING LAMP (FR) CARPET FLOOR (RR) CARPET FLOOR (FR-L) INTERIOR SALOON TOOL KIT CARPET BOLT CRANE AND JACK HEAD UNIT CARPET FLOOR (MID) CARPET FLOOR (FR-R)/FOG LAMP (L) FOG LAMP (R) DOOR REPAIR (RR-R) MIRROR (L) FENDER REPAIR (FR-R) BUMPER REPAIR (RR) EMBLEM TURN LAMP (RR-L) TAILLIGHT (RR-L) DOOR REPAIR (FR-R) DOOR REPAIR (RR-L) TURN LAMP (RR-R) LICENSE PLATE FENDER REPAIR (RR-L) TURN LAMP (FR-L) DOOR REPAIR (FR-L) SIDE SKIRT REPAIR (L) FENDER REPAIR (RR-R) HEADLIGHT (FR-R) TURN LAMP (FR-R) ROOF REPAIR MIRROR (R) WINDSHIELD WIPER ENGINE HOOD REPAIR SIDE SKIRT REPAIR (R) HEADLIGHT (FR-L) FENDER REPAIR (FR-L) BUMPER REPAIR (FR) DOOR REPAIR (TRUNK) TAILLIGHT (RR-R) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
24	DD 1406 RB	TOYOTA AGYA 1.0 G	2015	MT	998	MERAH	RP78.500.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-11-09	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
FOTO NOKA & NOSIN T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC ANDI ANDIRMAWANSAH 0853-1403-0379 // CS PUSAT 081188089292// MESIN TIDAK BERFUNGSI, BODY TERGORES, BAN CADANGAN T/A, ALAT MOBIL T/A, ACCU SOAK, ALARM T/A//RADIATOR RADIATOR FAN RIM (SPARE) REMOTE SPRING (RR) GASKET COVER HEAD TIRE (RR-R) GASKET CYLINDER HEAD TIRE (SPARE) RIM (RR-L) TIRE (FR-R) RACK STEER SPRING (FR) ENGINE SERVICES (LIGHT) BRAKE PAD (RR) BRAKE MASTER TIRE (RR-L) FAN BELT CLUTCH PLATE AIRCON EVAPORATOR BATTERY BRAKE PAD (FR) SPARK PLUG(S) TIRE (FR-L) INJECTOR CLUTCH BEARING/CEILING LAMP (FR) CEILING TRIM TOOL KIT CARPET FLOOR (RR) CARPET FLOOR (MID) INTERIOR SALOON CARPET CARPET FLOOR (FR-L) CARPET FLOOR (FR-R) BOLT CRANE AND JACK/MIRROR (L) MIRROR (R) TURN LAMP (FR-R) FOG LAMP (L) HEADLIGHT (FR-R) TURN LAMP (FR-L) HEADLIGHT (FR-L) RIM COVER (FR-L) FOG LAMP (R) RIM COVER (RR-L) SIDE SKIRT REPAIR (R) WINDSHIELD WIPER SIDE SKIRT REPAIR (L) DOOR REPAIR (TRUNK) FENDER REPAIR (RR-R) FENDER REPAIR (FR-L) FENDER REPAIR (RR-L) BUMPER REPAIR (RR) FENDER REPAIR (FR-R) BUMPER REPAIR (FR) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
25	PA 8413 GE	DAIHATSU GRAN MAX PICK-UP	2019	MT	1495	HITAM	RP53.500.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
NOPOL FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. NANDO / BPK FATUR 0852-7005-0894 / 0822-2759-3728 / CS PUSAT 081188089292// BODY BARET, BUMPER BARET, CAT KUSAM, NOSIN KARAT, BAK BARET KARAT, MESIN REMBES OLI, MESIN MATI RUSAK, TURUN MESIN.//CHECK ENGINE INDIKATOR ENGINE MOUNTING MUFFLER MAIN AXELS BRAKE MASTER INJECTOR ENGINE SERVICES (HEAVY) RIM (RR-L) DYNAMO STARTER RIM (SPARE) RIM (RR-R) RIM (FR-L) DISC PAD RIM (FR-R) RADIATOR FAN AIR FILTER SPRING (FR) CLUTCH PLATE TIRE (FR-L) RADIATOR SPRING (RR) WHEEL BEARING (FR) RACK STEER FUEL PUMP FAN BELT SHOCBREAKERS (RR) BATTERY BRAKE PAD (RR) SPARK PLUG(S) WHEEL BEARING (RR) GASKET COVER HEAD TIRE (FR-R) HEADER TIRE (RR-R) TIRE (RR-L) GASKET CYLINDER HEAD TIRE (SPARE) COIL IGNITION BRAKE PAD (FR) SHOCBREAKERS (FR) AIRCON EVAPORATOR/INTERIOR SALOON TOOL KIT BOLT CRANE AND JACK CARSEAT (FR-R)/FENDER REPAIR (FR-R) FENDER REPAIR (FR-L) GRILLES HEADLIGHT (FR-L) TURN LAMP (RR-R) BUMPER REPAIR (FR) TAILLIGHT (RR-R) CARGO PANEL REPAIR (RR) TAILLIGHT (RR-L) TURN LAMP (RR-L) TURN LAMP (FR-L) FRONT PANEL REPAIR TURN LAMP (FR-R) ROOF REPAIR HEADLIGHT (FR-R) DOOR REPAIR (FR-R) DOOR REPAIR (FR-L) CARGO PANEL REPAIR (DECK) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
26	DG 1936 NB	DAIHATSU XENIA	2011	MT	1298	ABU ABU METALIK	RP42.500.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
NOPOL FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK FAHMI/BPK. USMAN 0821-8761-0965 / 0823-9133-7272 / CS PUSAT 081188089292// BODY BARET, CAT KUSAM, CAT TERKELUPAS, BUMPER BARET PECAH IMITASI, INTERIOR KOTOR, JOK KOTOR, MESIN REMBES OLI, UNIT EX TAKSI ANTAR KABUPATEN, RUANG MESIN KOTOR, LAMPU KUSAM, BAN DAN VELG IMITASI, MOBIL CEPER, STIR RACING, HEAD UNIT IMITASI, PLAFON IMITASI, PILAR IMITAS, ATAP PENYOK.//RIM (RR-R) COIL IGNITION CLUTCH BEARING FAN BELT TIRE (FR-L) RIM (RR-L) SPRING (FR) TIRE (FR-R) RIM (FR-L) RIM (FR-R) TIRE (SPARE) SHOCBREAKERS (RR) TIRE (RR-R) SPRING (RR) HEADER GASKET COVER HEAD BRAKE PAD (FR) ENGINE SERVICES (HEAVY) SPARK PLUG(S) BATTERY TIRE (RR-L) RIM (SPARE) SHOCBREAKERS (FR) BRAKE MASTER INJECTOR GASKET CYLINDER HEAD DISC PAD RADIATOR FAN BRAKE PAD (RR) RADIATOR CLUTCH PLATE AIRCON EVAPORATOR RACK STEER/GEAR LEVER DOOR TRIM (RR-L) DOOR TRIM (FR-L) DOOR TRIM (FR-R) DOOR TRIM (RR-R) DOOR TRIM (TRUNK) CARSEAT (RR-L) CARSEAT (RR-R) HEADREST (FR-R) STEERING-WHEEL HEAD UNIT CARPET FLOOR (MID) CARPET FLOOR (FR-L) BOLT CRANE AND JACK CARPET FLOOR (RR) CARPET CEILING TRIM CARPET FLOOR (FR-R) INTERIOR SALOON TOOL KIT/RIM COVER (RR-L) RIM COVER (FR-R) RIM COVER (FR-L) WINDSHIELD WIPER RIM COVER (RR-R) FENDER REPAIR (RR-L) FENDER REPAIR (RR-R) SIDE SKIRT REPAIR (R) FENDER REPAIR (FR-L) FENDER REPAIR (FR-R) SIDE SKIRT REPAIR (L) HEADLIGHT (FR-L) ENGINE HOOD REPLACE DOOR REPAIR (RR-R) FOG LAMP (L) TURN LAMP (FR-R) TAILLIGHT (RR-R) MIRROR (L) MIRROR (R) GRILLES TURN LAMP (RR-R) TAILLIGHT (RR-L) EMBLEM LICENSE PLATE DOOR REPAIR (FR-L) HEADLIGHT (FR-R) BUMPER REPAIR (FR) FOG LAMP (R) DOOR REPAIR (TRUNK) TURN LAMP (FR-L) DOOR REPAIR (RR-L) ROOF REPAIR TURN LAMP (RR-L) BUMPER REPAIR (RR) DOOR REPAIR (FR-R) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	