

Daftar Lelang Floor Mobil - LELANG ONLINE VAGANZA TIMUR | 21/09/2026 (88)
KOTA LELANG ONLINE VAGANZA TIMUR (LOV) / -

KATALOG INI HANYA SEBAGAI PANDUAN SAJA. BUKAN SEBAGAI PEDOMAN ATAU SEBAGAI BAHAN ACUAN COMPLAIN

SmartBID melelang unit apa adanya, peserta lelang wajib melakukan cek fisik kendaraan dan dokumen dengan sebaik-baiknya. Pemenang lelang telah dianggap sudah memahami kondisi dan dokumen kendaraan yang telah dimenangkan. Deposit dan pelunasan unit Lelang SmartBID hanya melalui transfer Bank Central Asia, Tbk (BCA) a/n PT. Anugerah Lelang Indonesia, nomor rekening : 4688897988 (Sidoarjo), 4686088588 (Semarang), 4687088688 (Tangerang), 4688670088 (Makassar) .

Note:
Setiap unit dikenakan biaya administrasi sebesar: **Rp. 3.500.000,-**
Khusus untuk unit dengan harga terbentuk di atas **Rp. 350.000.000,-** dikenakan admin fee 1% dari harga terbentuk.

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
1	PB 1760 MA	TOYOTA AVANZA	2008	MT	1298	HITAM METALIK	RP29.500.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. IMMANUEL 0822-3903-7374 / CS PUSAT 081188089292// SPOILER (RR) , TURN LAMP (FR-R) , DOOR REPAIR (FR-R) , FOG LAMP (L) , RIM COVER (RR-R) , DOOR REPAIR (RR-R) , ROOF REPAIR , DOOR REPAIR (RR-L) , RIM COVER (FR-R) , HEADLIGHT (FR-R) , DOOR REPAIR (TRUNK) , BUMPER REPAIR (RR) , HEADLIGHT (FR-L) , BUMPER REPAIR (FR) , DOOR REPAIR (FR-L) , TURN LAMP (FR-L) , FOG LAMP (R) , ENGINE HOOD REPAIRBOLT CRANE AND JACK , CARSEAT (FR-L) , TOOL KIT , INTERIOR SALOON , STEERING-WHEEL , CARSEAT (FR-R) , HEAD UNITGASKET CYLINDER HEAD , CLUTCH PLATE , SPARK PLUG(S) , SPRING (RR) , BATTERY , ENGINE SERVICES (HEAVY) , BRAKE PAD (FR) , COIL IGNITION , FAN BELT , HEADER , TIRE (RR-R) , WHEEL BEARING (FR) , BRAKE PAD (RR) , TIRE (FR-L) , SHOCBREAKERS (RR) , TIRE (SPARE) , TIRE (FR-R) , SPRING (FR) , WHEEL AXELS (FR) , RADIATOR , SHOCBREAKERS (FR) , AIRCON EVAPORATOR , RACK STEER , WHEEL BEARING (RR) , GASKET COVER HEAD , CLUTCH BEARING , WHEEL AXELS (RR) , RADIATOR FAN , TIRE (RR-L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
2	AG 1163 WS	TOYOTA FORTUNER 2.7 G LUX	2012	AT	2694	HITAM METALIK	RP149.000.000	BENSIN	122814	D	C	C	14 HARI KERJA	ADA 2026-04-21	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC FIRMAN 62 812-3674-7297 / CHANDRA 0878-6190-3208 // //CASHBACK SEBESAR:RP3,500,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
3	W 1041 DS	TOYOTA INNOVA G	2015	AT	1998	SILVER METALIK	RP143.000.000	BENSIN	149689	C	C	C	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC AWAL +62 895-3231-57272 / ANDRI 085136886212 // //CASHBACK SEBESAR:RP3,500,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
4	DT 8353 AM	HINO XZU349R	2022	MT	4009	HIJAU	RP204.500.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-10-12	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. FERDY 0822-4916-6365 //CS PUSAT 081188089292// MESIN TIDAK BERFUNGSI, DINAMO STARTER RUSAK, INDIKATOR CEK ENGINE MENYALA, BAN CADANGAN T/A, HEAD UNIT T/A, ALAT MOBIL T/A, DUMP PENYOK, ACCU RUSAK, DASHBOARD TIDAK LENGKAP, SETIR IMITASI, TUAS PERSNELING IMITASI, COVER PLAFON IMITASI, LANTAI KABIN BERKARAT & KEROPOS, JOK SOBEK, MESIN REMBES OLI//CEK ENGINE LIGHT SPRING (RR) RIM (SPARE) ENGINE SERVICES (LIGHT) TIRE (RR-R) OUT DYNAMO STARTER GASKET COVER HEAD AIR FILTER COIL IGNITION GASKET CYLINDER HEAD TIRE (FR-L) TIRE (RR-L) IN SPARK PLUG(S) SPRING (FR) BRAKE PAD (FR) TIRE (RR-L) OUT RADIATOR TIRE (RR-R) IN FAN BELT TIRE (SPARE) CLUTCH PLATE BATTERY BRAKE MASTER BRAKE PAD (RR) INJECTOR RADIATOR FAN TIRE (FR-R)/GEAR LEVER COVER CARPET BOLT CRANE AND JACK TOOL KIT REAR VIEW MIRROR CEILING TRIM INTERIOR SALOON HEAD UNIT CARSEAT (FR-L) CARSEAT (FR-R) STEERING-WHEEL DASHBOARD/HEADLIGHT (FR-L) HEADLIGHT (FR-R) TURN LAMP (RR-R) ANTENNA CARGO PANEL REPAIR (RR) FOG LAMP (R) TAILLIGHT (RR-R) TURN LAMP (FR-L) FRONT PANEL REPAIR TURN LAMP (FR-R) DOOR REPAIR (FR-L) WINDSHIELD WIPER TAILLIGHT (RR-L) CABIN REPAIR TURN LAMP (RR-L) BUMPER REPAIR (FR) MIRROR (L) MIRROR (R) DOOR REPAIR (FR-R) FOG LAMP (L) EMBLEM ROOF REPAIR CARGO PANEL REPAIR (DECK) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
5	PS 8240 A	TOYOTA HILUX 2.4G DC	2022	MT	2393	PUTIH	RP82.500.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
NOPOL FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. DEDY PAKPAHAN 0812 7358 6232 // CS PUSAT 081188089292// MESIN TIDAK BERFUNGSI (TERBONGKAR). KOMPONEN MESIN TIDAK LENGKAP, BAN CADANGAN T/A, ALAT MOBIL T/A, VELG IMITASI, BAN GUNDUL, SETIR KUSAM, SEATBELT T/A, HEADREST TIDAK LENGKAP, DASHBOARD RUSAK & KUSAM//GEAR BOX GEAR BOX OVERHAUL SPRING (RR) TIRE (SPARE) TIRE (FR-R) RIM (RR-L) ENGINE BLOCK HEAD RIM (RR-R) FAN BELT AIRCON EVAPORATOR POWER STEERING RIM (FR-L) SPRING (FR) COIL IGNITION TIRE (FR-L) RACK STEER RIM (SPARE) ENGINE BLOCK FR-APRON DYNAMO STARTER MUFFLER CLUTCH PLATE GASKET CYLINDER HEAD RADIATOR ENGINE SERVICES (HEAVY) AIR FILTER GASKET COVER HEAD AIRBAG RIM (FR-R) TIRE (RR-R) INJECTOR RADIATOR FAN BRAKE PAD (FR) REMOTE TIRE (RR-L) SPARK PLUG(S) BRAKE PAD (RR) BRAKE MASTER SPARE KEY (IMMOBILIZER) BATTERY/CARPET INTERIOR SALOON SEATBELT (RR-R) SEATBELT (FR-L) HEADREST (RR-R) SEATBELT (RR-L) BOLT CRANE AND JACK TOOL KIT SEATBELT (FR-R) HEADREST (RR-L) CEILING LAMP (FR) CEILING TRIM HEAD UNIT STEERING-WHEEL DASHBOARD AIRCON PANEL/CABIN REPAIR CARGO PANEL REPAIR (RR) LICENSE PLAT ANTENNA FOG LAMP (R) DOOR REPAIR (FR-L) RIM COVER (RR-L) RIM COVER (RR-R) CARGO PANEL REPAIR (DECK) MIRROR (L) RIM COVER (RR-R) CARGO PANEL REPAIR (RR-R) TAILLIGHT (RR-R) RIM COVER (FR-R) RIM COVER (FR-L) EMBLEM FOG LAMP (L) WINDSHIELD WIPER CARGO PANEL REPAIR (RR-L) TURN LAMP (RR-R) HEADLIGHT (FR-L) MIRROR (R) FENDER REPAIR (FR-L) BUMPER REPLACE (FR) SIDE SKIRT REPAIR (L) TURN LAMP (RR-L) DOOR REPAIR (FR-R) HEADLIGHT (FR-R) ENGINE HOOD REPLACE SIDE SKIRT REPAIR (R) FENDER REPAIR (FR-R) TURN LAMP (FR-R) GRILLES TAILLIGHT (RR-L) ROOF REPAIR TURN LAMP (FR-L) DOOR REPAIR (RR-R) DOOR REPAIR (RR-L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
6	PB 1727 MM	TOYOTA INNOVA G	2015	MT	1998	PUTIH	RP121.500.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. IMMANUEL 0822-3903-7374 / CS PUSAT 081188089292// BODY BARET PENYOK, BUMPER BARET, CAT KUSAM, BAN IMITASI, SARUNG JOK IMITASI, INTERIOR KUSAM, BUMPER BARET, MESIN REMBES, KARPET TIDAK LENGKAP,HEAD UNIT IMITASI//CLUTCH BEARING SPRING (FR) COIL IGNITION WHEEL BEARING (RR) SHOCBREAKERS (RR) TIRE (FR-R) TIRE (RR-L) HEADER ENGINE SERVICES (HEAVY) WHEEL BEARING (FR) TIRE (FR-L) RADIATOR FAN INJECTOR SHOCBREAKERS (FR) RIM (RR-R) SPRING (RR) TIRE (RR-R) CLUTCH PLATE RADIATOR GASKET COVER HEAD DISC PAD RIM (SPARE) RIM (FR-L) AIRCON EVAPORATOR GASKET CYLINDER HEAD RIM (RR-L) RACK STEER BRAKE MASTER FUEL PUMP RIM (FR-R) BATTERY FAN BELT TIRE (SPARE) BRAKE PAD (RR) BRAKE PAD (FR) SPARK PLUG(S)/CARPET FLOOR (FR-R) CARPET FLOOR (MID) INTERIOR SALOON TOOL KIT BOLT CRANE AND JACK CARSEAT (FR-R) CARPET FLOOR (RR) HEAD UNIT CARSEAT (FR-L) CARPET FLOOR (FR-L) CARPET/DOOR REPAIR (RR-R) HEADLIGHT (FR-R) TURN LAMP (RR-L) FOG LAMP (L) TAILLIGHT (RR-L) TURN LAMP (RR-R) TAILLIGHT (RR-R) DOOR REPAIR (TRUNK) DOOR REPAIR (RR-L) HEADLIGHT (FR-L) BUMPER REPAIR (FR) BUMPER REPAIR (RR) FOG LAMP (R) DOOR REPAIR (FR-L) ENGINE HOOD REPAIR LICENSE PLATE TURN LAMP (FR-L) TURN LAMP (FR-R) ROOF REPAIR DOOR REPAIR (FR-R) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
7	L 1136 JI	HONDA JAZZ GK5 1.5 S AT CKD	2017	AT	1496	MERAH	RP152.000.000	BENSIN	55518	C	C	C	14 HARI KERJA	ADA 2025-06-13	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC AWAL +62 895-3231-57272 / ANDRI 085136886212 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
8	DH 8254 G	MITSUBISHI FE 74 HD	2009	MT	3908	KUNING	RP96.000.000	SOLAR	0	D	D	D	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
NOPOL PADA FISIK T/A // ADA PERBEDAAN FIISK PADA BPKB JENIS LIGHT TRUK SEDANGKAN PADA FISIK DUMP TRUK // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC PAK NATAN 081338280981 / INSPEKSI PAK GAD 085338212232 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
9	DH 1213 HN	TOYOTA INNOVA G	2021	MT	1998	SILVER METALIK	RP263.000.000	BENSIN	83978	C	C	C	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC PAK NATAN 081338280981 / INSPEKSI PAK GAD 085338212232 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
10	DD 1079 SN	HONDA MOBILIO DD4 1.5 RS	2015	AT	1496	MERAH TUA MUTIARA	RP92.500.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2027-02-02	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. AGUS 0823-4704-2525 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES, ALAT MOBIL T/A, HEAD UNIT IMITASI, MESIN REMBES OLI//SPRING (FR) WHEEL BEARING (FR) TIRE (RR-L) WHEEL BEARING (RR) GASKET COVER HEAD RADIATOR TIRE (RR-R) SPRING (RR) GASKET CYLINDER HEAD RADIATOR FAN TIRE (SPARE) TIRE (FR-L) ENGINE SERVICES (LIGHT) TIRE (FR-R) FAN BELT CLUTCH BEARING SPARE KEY (IMMOBILIZER) CLUTCH PLATE BRAKE PAD (FR) AIRCON EVAPORATOR BRAKE MASTER INJECTOR BRAKE PAD (RR) BATTERY SPARK PLUG(S)/CEILING LAMP (RR) CEILING LAMP (FR) CARPET FLOOR (FR-R) CARPET FLOOR (RR) BOLT CRANE AND JACK CARPET FLOOR (FR-L) HEAD UNIT CARPET FLOOR (MID) CEILING TRIM TOOL KIT AIRCON PANEL INTERIOR SALOON CARPET/TURN LAMP (RR-R) TAILLIGHT (RR-R) TAILLIGHT (RR-L) TURN LAMP (FR-R) WINDSHIELD WIPER MIRROR (L) FOG LAMP (L) ENGINE HOOD REPAIR TURN LAMP (RR-L) HEADLIGHT (FR-L) TURN LAMP (FR-L) FOG LAMP (R) HEADLIGHT (FR-R) MIRROR (R) DOOR REPAIR (TRUNK) SIDE SKIRT REPAIR (R) EMBLEM BUMPER REPAIR (RR) FENDER REPAIR (FR-R) SIDE SKIRT REPAIR (L) FENDER REPAIR (FR-L) FENDER REPAIR (RR-L) FENDER REPAIR (RR-R) BUMPER REPAIR (FR) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
11	PA 1653 KQ	TOYOTA INNOVA G	2013	MT	1998	PUTIH	RP35.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN			
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. DEDY 0812-7358-6232 / CS PUSAT 081188089292// UNIT LAKA LANTAS, MESIN TIDAK BERFUNGSI, KOMPONEN MESIN TIDAK LENGKAP & RUSAK, CHASIS PENYOK, INDIKASI ECU T/A, PINTU KANAN T/A, KACA DEPAN T/A, KAP MESIN TERLEPAS & RUSAK, BODY PENYOK, AS RODA RUSAK, DASHBOARD RUSAK & TIDAK LENGKAP, HEAD UNIT RUSAK, BULLHEAD PENYOK, RADIATOR RUSAK//TIRE (RR-R) FR-APRON SPRING (FR) TIRE (FR-L) R-APRON TIRE (RR-L) RIM (FR-R) L-APRON CLUTCH PLATE TIRE (FR-R) CLUTCH BEARING POWER STEERING TIRE (SPARE) FAN BELT BRAKE PAD (FR) GASKET COVER HEAD RACK STEER AIRBAG SENSOR RADIATOR FAN MUFFLER INJECTOR RIM (RR-R) BRAKE PAD (RR) ENGINE SERVICES (HEAVY) DISC PAD GASKET CYLINDER HEAD ENGINE BLOCK RADIATOR RIM (FR-L) RIM (RR-L) BRAKE MASTER WHEEL AXELS (RR) AIRCON EVAPORATOR SPARK PLUG(S) RIM (SPARE) ECU AIRBAG DYNAMO STARTER BATTERY WHEEL AXELS (FR)/GEAR LEVER CENTRAL LOCK HORN CARPET FLOOR (FR-R) CARPET FLOOR (MID) CARPET FLOOR (RR) INTERIOR SALOON FR-R DOOR LOCK CARPET FLOOR (FR-L) INTERIOR MIRROR GEAR LEVER COVER POWER-WINDOW PANEL (RR-L) BOLT CRANE AND JACK TOOL KIT CEILING LAMP (FR) CARPET POWER-WINDOW PANEL (RR-R) ELECTRIC-MIRROR PANEL POWER-WINDOW PANEL (FR-L) STEERING-WHEEL CEILING TRIM DASHBOARD POWER-WINDOW PANEL (DRV) DOOR TRIM (FR-R) CEILING LAMP (RR) HEAD UNIT AIRCON PANEL COMBINATION METER/TAILLIGHT (RR-R) EMBLEM TURN LAMP (RR-L) ROOF REPAIR DOOR REPLACE (FR-R) MIRROR (L) RIM COVER (FR-R) ANTENNA ENGINE HOOD REPLACE RR-QUARTER GLASS (R) FENDER REPAIR (RR-L) TURN LAMP (FR-L) GRILLES FR-VENT GLASS (R) WINDSHIELD WIPER DOOR REPAIR (RR-R) TAILLIGHT (RR-L) FOG LAMP (L) FENDER REPLACE (FR-R) RIM COVER (FR-L) RIM COVER (RR-L) FR-VENT GLASS (L) MIRROR (R) DOOR REPAIR (TRUNK) HEADLIGHT (FR-R) WINDSHIELD GLASS FENDER REPAIR (RR-R) RR-DOOR GLASS (L) RR-VENT GLASS (L) FOG LAMP (R) RR-DOOR GLASS (R) TURN LAMP (FR-R) ELECTRIC MIRROR (R) SPOILER (RR) LICENSE PLATE DOOR REPAIR (RR-L) DOOR REPAIR (FR-L) SIDE SKIRT REPAIR (R) FR-DOOR GLASS (R) RIM COVER (RR-R) HEADLIGHT (FR-L) TURN LAMP (RR-R) DOOR HANDLE (FR-R) FENDER REPAIR (FR-L) BUMPER REPAIR (RR) FR-DOOR GLASS (L) RR-VENT GLASS (R) BUMPER REPLACE (FR) ELECTRIC MIRROR (L) EX-ACCIDENT SIDE SKIRT REPAIR (L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																		
12	B 2663 UFY	TOYOTA AVANZA E	2017	AT	1329	MERAH METALIK	RP68.500.000	BENSIN	0	-	-	-	14 HARI KERJA	-	T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
																KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. ANDIRMAWANSYAH 0852-9971-7153 CS PUSAT 081188089292// UNIT LAKA LANTAS, BODY PENYOK, KACA DEPAN & BELAKANG PECAH, KACA JENDELA KANAN PECAH, AIRBAG PECAH, HEAD UNIT T/A, BULLHEAD PENYOK, SEATBELT TIDAK LENGKAP, RADIATOR RUSAK, CHASIS DEPAN PENYOK, BAN CADANGAN T/A, ALAT MOBIL T/A, ACCU T/A, KLAKSON T/A//TIRE (RR-R) TIRE (SPARE) SPRING (FR) TIRE (FR-R) SPARE KEY (IMMOBILIZER) WHEEL AXELS (RR) RIM (SPARE) CLUTCH PLATE RADIATOR FAN BRAKE MASTER ENGINE MOUNTING R-APRON ENGINE SERVICES (LIGHT) GASKET COVER HEAD TIRE (FR-L) WHEEL AXELS (FR) SPARK PLUG(S) FR-APRON TIRE (RR-L) BRAKE PAD (RR) SPRING (RR) AIRBAG RADIATOR FAN BELT GASKET CYLINDER HEAD AIRCON EVAPORATOR AIRBAG SENSOR CLUTCH BEARING BATTERY BRAKE PAD (FR) INJECTOR RACK STEER/DOOR TRIM (TRUNK) CENTRAL LOCK POWER-WINDOW PANEL (DRV) AIRCON PANEL BOLT CRANE AND JACK INTERIOR SALOON HORN TOOL KIT ELECTRIC-MIRROR PANEL CARPET FLOOR (FR-L) INTERIOR MIRROR POWER-WINDOW PANEL (RR-R) HEAD UNIT STEERING-WHEEL CARPET CARPET FLOOR (MID) CARPET FLOOR (RR) CARPET FLOOR (FR-R) CEILING LAMP (FR) CEILING LAMP (RR) SEATBELT (RR-L) DASHBOARD CEILING TRIM/TURN LAMP (RR-L) SPOILER (RR) RIM COVER (FR-R) EMBLEM RIM COVER (RR-L) DOOR REPAIR (RR-L) HEADLIGHT (FR-L) MIRROR (L) WINDSHIELD WIPER EX-ACCIDENT TURN LAMP (RR-R) ANTENNA DOOR REPAIR (FR-L) FENDER REPAIR (FR-L) DOOR REPLACE (FR-R) FOG LAMP (R) RIM COVER (FR-L) RIM COVER (RR-R) SIDE SKIRT REPAIR (R) ROOF REPLACE LICENSE PLATE HEADLIGHT (FR-R) FR-DOOR GLASS (R) FOG LAMP (L) BACK GLASS WINDSHIELD GLASS RR-DOOR GLASS (R) DOOR REPAIR (RR-R) SIDE SKIRT REPAIR (L) GRILLES ENGINE HOOD REPLACE FENDER REPLACE (RR-R) ELECTRIC MIRROR (R) TAILLIGHT (RR-R) TURN LAMP (FR-R) TAILLIGHT (RR-L) BUMPER REPLACE (FR) DOOR REPLACE (TRUNK) TURN LAMP (FR-L) BUMPER REPLACE (RR) MIRROR (R) FENDER REPAIR (RR-L) FENDER REPLACE (FR-R) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																		
13	PB 1623 MF	TOYOTA INNOVA G	2017	MT	1998	HITAM METALIK	RP207.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-02-22		KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
																KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. IMMANUEL 0822-3903-7374 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES, VELG & BAN IMITASI, ALAT MOBIL T/A//REMOTE WHEEL BEARING (RR) WHEEL BEARING (FR) TIRE (RR-L) RIM (RR-L) RIM (FR-L) SPRING (FR) TIRE (FR-L) TIRE (RR-R) SPARK PLUG(S) RIM (FR-R) RIM (SPARE) CLUTCH PLATE GASKET COVER HEAD RIM (RR-R) BRAKE PAD (FR) TIRE (FR-R) RADIATOR FAN BRAKE MASTER AIRCON EVAPORATOR FAN BELT TIRE (SPARE) INJECTOR ENGINE SERVICES (LIGHT) GASKET CYLINDER HEAD SPRING (RR) BATTERY CLUTCH BEARING BRAKE PAD (RR) SPARE KEY (IMMOBILIZER) RADIATOR/AIRCON PANEL CARPET FLOOR (FR-R) TOOL KIT BOLT CRANE AND JACK CARPET FLOOR (MID) CEILING LAMP (RR) CARPET FLOOR (FR-L) CEILING TRIM CARPET CARPET FLOOR (RR) CEILING LAMP (FR) INTERIOR SALOON/RIM COVER (RR-R) FENDER REPAIR (RR-L) TAILLIGHT (RR-R) ENGINE HOOD REPAIR FENDER REPAIR (FR-L) RIM COVER (FR-L) TURN LAMP (RR-R) DOOR REPAIR (TRUNK) MIRROR (L) TURN LAMP (FR-L) EMBLEM MIRROR (R) HEADLIGHT (FR-L) HEADLIGHT (FR-R) TAILLIGHT (RR-L) RIM COVER (FR-R) WINDSHIELD WIPER RIM COVER (RR-L) FENDER REPAIR (RR-R) TURN LAMP (FR-R) TURN LAMP (RR-L) FENDER REPAIR (FR-R) SIDE SKIRT REPAIR (L) SIDE SKIRT REPAIR (R) BUMPER REPAIR (FR) BUMPER REPAIR (RR) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																		
14	DP 1481 PE	HONDA JAZZ GE8 1.5 E	2012	MT	1496	MERAH	RP96.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-07-23		KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
																KEUR T/A	SPH T/A	FORM A T/A
ADA PERBEDAAN NOPOL PADA FISIK & STNK DP1481PE PADA DOKUMEN DP577CZ // TIDAK ADA LEMBAR PERUBAHAN NOPOL PADA BPKB // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. AGUS 0823-4704-2525 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES & SEBAGIAN DI STICKER, ALARM T/A, AC TIDAK DINGIN, KLAKSON TIDAK BERFUNGSI, BAN CADANGAN T/A, SPOILER T/A, ALAT MOBIL T/A, HEADREST TIDAK LENGKAP, HEAD UNIT IMITASI, SEATBELT TIDAK LENGKAP, MESIN REMBES OLI//TIRE (FR-R) INJECTOR GASKET COVER HEAD RACK STEER AIRCON EVAPORATOR WHEEL BEARING (RR) SHOCBREAKERS (FR) TIRE (RR-L) FAN BELT WHEEL BEARING (FR) ENGINE SERVICES (LIGHT) BRAKE MASTER SPRING (FR) BATTERY SHOCBREAKERS (RR) TIRE (FR-L) SPARK PLUG(S) BRAKE PAD (FR) REMOTE RADIATOR FAN SPRING (RR) RIM (SPARE) TIRE (RR-R) BRAKE PAD (RR) GASKET CYLINDER HEAD CLUTCH BEARING TIRE (SPARE) RADIATOR CLUTCH PLATE/CARPET FLOOR (MID) INTERIOR SALOON HEADREST (FR-R) HORN CARPET FLOOR (FR-R) TOOL KIT SEATBELT (RR-L) CARPET FLOOR (FR-L) CARPET FLOOR (RR) SEATBELT (RR-L) BOLT CRANE AND JACK HEADREST (FR-L) CEILING LAMP (FR) HEAD UNIT CARPET CEILING TRIM AIRCON PANEL/FOG LAMP (R) TAILLIGHT (RR-R) TURN LAMP (RR-R) SPOILER (RR) HEADLIGHT (FR-R) TAILLIGHT (RR-L) TURN LAMP (FR-L) LICENSE PLATE TURN LAMP (RR-L) EMBLEM WINDSHIELD WIPER ANTENNA GRILLES FOG LAMP (L) HEADLIGHT (FR-L) ROOF REPAIR SIDE SKIRT REPAIR (L) MIRROR (L) BUMPER REPAIR (RR) DOOR REPAIR (FR-L) DOOR REPAIR (RR-R) SIDE SKIRT REPAIR (R) FENDER REPAIR (RR-L) MIRROR (R) FENDER REPAIR (FR-L) ENGINE HOOD REPAIR FENDER REPAIR (RR-R) DOOR REPAIR (FR-R) FENDER REPAIR (FR-R) DOOR REPAIR (TRUNK) DOOR REPAIR (RR-L) BUMPER REPAIR (FR) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																		